

Summary

Introduction	1
--------------------	---

Chapter I : General thermodynamic aspects

I-1- Introduction.....	3
I-2- Kinetics of a transformation	3
I-3- Activated transition state	5
I-4- Internal activation energy.....	6
I-5- Distribution of kinetic energy	7
I-6- Study of the kinetics of a reaction	8
Practice exercise	10

Chapter II : Crystal growth and solidification

II-1- Introduction.....	11
II-2- Liquid state and solid state	11
II-3- Solid/liquid interface	12
II-3-1- Germination.....	14
II-3-2 Growth	23
II-4- Solidification structures	32
Practice exercise.....	34

Chapter III: General classification of phase transformations and new phase germination problems

III-1- Introduction.....	36
--------------------------	----

III-2-	General classification of phase transformations	37
III-3-	New phase germination problems	38

Chapter IV: Kinetics of transformations in materials and alloys in the solid state

IV-1-	Introduction.....	40
IV-2-	General characteristics of solid-state transformations	40
IV-3-	Initiation of reactions proceeding by germination and growth	41
IV-4-	Classical theory of germination	42
IV-4-1.	Homogeneous germination	42
IV-4-2.	Heterogeneous germination	44
IV-5-	Description of the global behavior of phase transformations by Avrami's theory.	46
IV-6-	Diagrams TTT (Transformation/Time/Temperature).....	47
IV-7-	Spinodal decomposition theory	50
IV-7-1.	Spinodal decomposition definition	50
IV-7-2.	Mode of decomposition	52
IV-8-	Insufficiency of previous theories.....	54
	Practice exercise.....	55

Chapter V: Role of elastic strain energy and interface energy

V-1-	Introduction.....	57
V-2-	Total coherently, semi-coherently and total incoherently	57
V-3-	Characteristics of the phases formed by precipitation	61
V-4-	Misfit Strain effects	65
V-5-	Loss of coherence	68
	Practices exercise.....	71

Chapter VI: Mechanisms of crystal growth during diffusionless transformations

VI-1-	Introduction.....	73
-------	-------------------	----

VI-2-	Normal transformation	74
VI-3-	Martensitic transformation	74
VI-3-1.	General characteristics of martensitic transformation	76
VI-3-2.	Thermodynamic aspect of martensitic transformation	77
VI-4-	Massive transformation.....	79
	Practices exercise.....	81

Chapter VII: Types of diffusional transformations

VII-1-	Introduction.....	82
VII-2-	Definition of precipitation.....	82
VII-3-	Precipitation characteristics.....	84
VII-3-1.	Composition criteria and sequence of heat treatments for alloys.....	84
VII-3-2.	Precipitation sequence in quenching aluminum alloys.....	87
VII-4-	Types of precipitation in metal alloys.....	87
VII-4-1.	Continuous precipitation.....	87
VII-4-2.	Discontinuous precipitation.....	89
VII-5-	Precipitation mechanisms.....	91
VII-5-1.	Precipitation by germination and growth.....	91
VII-5-2.	Precipitation by spinodal decomposition	93
VII-6-	Experimental methods for studying structural precipitation.....	95
VII-6-1.	Metallography	95
VII-6-2.	X-ray and neutron diffraction.....	98
VII-6-3.	Macroscopic physical methods.....	98
	Practice exercise.....	101
	Terminologies.....	102
	References.....	116