

Contents

Introduction	1
--------------------	---

Chapter I : General thermodynamic aspects

I-1- Introduction.....	3
I-2- Transformation kinetics	3
I-3- Activated state	5
I-4- Internal activation energy.....	6
I-5- Distribution of kinetic energy	7
I-6- Study of the reaction kinetics	8
Practice exercise and answers	10

Chapter II : Crystal growth and solidification

II-1- Introduction.....	12
II-2- Liquid state and solid state	12
II-3- Solid/liquid interface	13
II-3-1- Nucleation.....	15
II-3-2 Growth	24
II-4- Solidification structures	32
Practice exercises and answers	34

Chapter III: General classification of phase transformations and issues related to new phase nucleation.

III-1- Introduction.....	40
III-2- General classification of phase transformations	41
III-3- New phase Nucleation problems	42

Chapter IV: Kinetics of Phase Transformations in Solid Materials and Alloys

IV-1-	Introduction.....	44
IV-2-	General characteristics of solid-state transformations	44
IV-3-	Initiation of reactions proceeding by nucleation and growth	45
IV-4-	Classical theory of nucleation	46
IV-4-1.	Homogeneous nucleation	46
IV-4-2.	Heterogeneous nucleation	48
IV-5-	Description of the global behavior of phase transformations by Avrami's theory.	50
IV-6-	Diagrams TTT (Transformation/Time/Temperature).....	51
IV-7-	Spinodal decomposition theory	54
IV-7-1.	Spinodal decomposition definition	54
IV-7-2.	Mode of decomposition	56
IV-8-	Limitations of previous theories.....	57
	Practice exercises and answers.....	59

Chapter V: Role of elastic strain energy and Interfacial energy

V-1-	Introduction.....	64
V-2-	Total coherently, semi-coherently and total incoherently	64
V-3-	Characteristics of the phases formed by precipitation	68
V-4-	Misfit Strain effects	71
V-5-	Loss of coherence	75
	Practices exercises and answers.....	77

Chapter VI: Mechanisms of crystal growth during diffusionless transformations

VI-1-	Introduction.....	80
VI-2-	Normal transformation	81
VI-3-	Martensitic transformation	81

VI-3-1.	General characteristics of martensitic transformation	83
VI-3-2.	Thermodynamic aspect of martensitic transformation	84
VI-4-	Massive transformation.....	86
	Practices exercises and answers	88

Chapter VII: Types of diffusional transformations

VII-1-	Introduction.....	89
VII-2-	Definition of precipitation.....	89
VII-3-	Characteristics of precipitation	91
VII-3-1.	Criteria for composition and sequence of heat treatments for alloys.....	91
VII-3-2.	Precipitation sequence in quenching aluminum alloys.....	94
VII-4-	Types of precipitation in metal alloys.....	95
VII-4-1.	Continuous precipitation.....	95
VII-4-2.	Discontinuous precipitation.....	96
VII-5-	Precipitation mechanisms.....	98
VII-5-1.	Precipitation by germination and growth.....	98
VII-5-2.	Precipitation by spinodal decomposition	100
VII-6-	Experimental methods for studying structural precipitation.....	102
VII-6-1.	Metallography	102
VII-6-2.	X-ray and neutron diffraction.....	105
VII-6-3.	Macroscopic physical methods.....	105
	Practice exercise and answer.....	101
	Terminologies.....	110
	References.....	124